



syn1588<sup>®</sup>

syn1588<sup>®</sup> Linux Live System

# Release Notes

Version 1.10 – October 30<sup>th</sup> 2018

**Oregano Systems – Design & Consulting GesmbH**

Franzosengraben 8, A-1030 Vienna

P: +43 (676) 84 31 04-300

F: +43 (1) 2533033-6162

@: [contact@oregano.at](mailto:contact@oregano.at)

W: <http://oregano.at>

## 0.1 Legals

Copyright © 2008-2018 Oregon Systems – Design & Consulting GesmbH

ALL RIGHTS RESERVED.

Oregon Systems does not assume any liability arising out of the application or use of any product described or shown herein nor does it convey any license under its patents, copyrights, or any rights of others.

Licenses or any other rights such as, but not limited to, patents, utility models, trademarks or tradenames, are neither granted nor conveyed by this document, nor does this document constitute any obligation of the disclosing party to grant or convey such rights to the receiving party.

Oregon Systems reserves the right to make changes, at any time without notice, in order to improve reliability, function or design. Oregon Systems will not assume responsibility for the use of any circuitry described herein.

All trademarks used in this document are the property of their respective owners.

## 0.2 Contents

1	Release 2018-10-29.....	3
2	Further Information.....	5

## 1 Release 2018-10-29

### 1.1 Change log syn1588® PTP Stack (V 1.7-14 Rev gc10fa03)

- 86eb2f5a9d: Added support for G8275\_1 and G8275\_2 profiles for Windows
- 850c48664e: Implement layer 2 mode for Windows
- 5253479dae: Fix lucky packet filter
- a37846e04c: Fix offset compensation in P2P mode
- abc785453c: Fix parser error message when domain is out of range
- 4ce4b83a9b: Fix segmentation fault in layer 2 mode for Linux
- d6d39e21d: Fix BMCA failure
- 5d836ada3e: Update parser testcase reference
- F21aa64c59: Add support to handle CTRL-BREAK signal for Windows
- 3ec4db0d04: Fix bug in Management Handler
- bb8d79e6b: Finished implementation of profile C37.238-2017
- 887573b90e: Remove internal management port

### 1.2 Change log for ptpmmm (V 1.7-14 Rev gc10fa03)

- 3ec4db0d04: Fix bug in Management Handler

### 1.3 Change log for ISync (V 1.7-14 Rev gc10fa03)

- Dbfbaca954: Fix issue when handing event inputs

### 1.4 Change log for eSync (V 1.7-14 Rev gc10fa03)

- Dbfbaca954: Fix issue when handing event inputs

### 1.5 Change log for fSync (V 1.7-14 Rev gc10fa03)

- No changes

## 1.6 Change log for vSync (V 1.7-14 Rev gc10fa03)

- No changes

## 1.7 Change log for syn1588 app (V 1.7-14 Rev gc10fa03)

- No changes

## 1.8 Change log for syn1588® PTPMMM GUI (v1.6-206-ga026da8)

- a026da86a8: Fix parsing of time properties dataset
- 37b304bb11: Fix issue: PTPMMM GUI stops working after midnight

## 1.9 Change log syn1588® PCIe NIC Linux driver (1.7-0-g1293164)

- 1e5ad520c4: add "blacklist\_altera\_cvp.sh" to blacklist the altera\_cvp kernel module
- 391d58695d: Update driver to support kernel version 4.15+

## 1.10 Known Issues

### 1.10.1 Leap Seconds Regression:

During our current release tests, we detected a regression in our Leap Seconds handling code.

#### 1.10.1.1 Affected products:

The issue only affects the syn1588® PTP-Stack when it is running in software mode.

If you are running our syn1588® PTP-Stack in combination with our syn1588® PCIe NIC or one of our syn1588® IP cores you are not affected by this regression.

#### 1.10.1.2 Known effects of this regression:

The premonition phase of a leap second starts 24 hours before the leap second and ends with the leap second event itself.

If a syn1588® PTP-Stack is started in Slave mode during the premonition phase of an upcoming leap second, the syn1588® PTP-Stack will fail to properly respond to the leap second.

This will lead to a discontinuity in the offset of the syn1588® PTP-Stack of about one second at the time of the leap second.

The control loop of the syn1588® PTP-Stack will readjust itself after this event.

If the syn1588® PTP-Stack running in Slave mode was started before the premonition phase, the syn1588® PTP-Stack will properly respond to the leap second and there will be no discontinuity.

If you have any further questions related to this issue, please contact us at [support@oreganosystems.at](mailto:support@oreganosystems.at)

## 2 Further Information

You are looking for further information about our syn1588® product line-up? Please contact Oregano Systems support! We will be pleased to provide you all the required information.



Franzosengraben 8

A-1030 Vienna

AUSTRIA

<http://oregano.at>

[contact@oregano.at](mailto:contact@oregano.at)